



Actual Noise Levels During Measurement				Noise Measurement Results in Leq%				
1-25	26-50	51-75	76-100	L%	1-25	26-50	51-75	76-100
56.0	57.4	55.7	57.6	L ₉₉	62.4	61.5	58.9	59.5
56.8	57.9	58.9	56.7		60.4	60.7	58.5	59.1
62.4	60.7	57.6	57.0	L ₉₀	60.1	59.1	58.3	59.1
60.1	59.1	56.8	56.8		58.9	59.1	58.2	59.0
58.8	58.1	57.8	56.7		58.8	58.9	58.0	58.9
58.4	58.8	57.8	59.1		58.5	58.8	58.0	58.4
58.1	58.9	58.0	57.6		58.4	58.4	57.9	58.3
57.2	56.9	58.5	58.0		58.4	58.1	57.8	58.1
60.4	57.9	58.2	59.0		58.1	58.0	57.8	58.1
56.7	57.2	57.9	58.4		57.9	57.9	57.6	58.0
55.9	58.0	58.3	58.9		57.8	57.9	57.3	57.6
57.3	57.2	57.3	57.5	L ₅₀	57.3	57.6	56.8	57.6
56.3	55.5	55.9	58.1		57.2	57.4	56.4	57.5
56.7	57.6	54.8	57.3		56.9	57.2	56.2	57.3
55.7	56.3	55.1	58.3		56.8	57.2	56.2	57.3
55.3	59.1	56.0	59.1		56.7	57.1	56.0	57.0
55.4	57.1	55.7	58.1		56.7	57.0	56.0	57.0
55.2	56.8	54.8	57.0		56.4	56.9	55.9	56.8
56.9	57.0	54.3	56.3		56.3	56.8	55.7	56.7
57.8	58.4	55.6	55.9	L ₂₅	56.0	56.5	55.7	56.7
56.4	55.9	56.4	55.8		55.9	56.3	55.6	56.5
57.9	56.0	58.0	54.6		55.7	56.0	55.1	56.3
58.5	55.9	56.2	56.5	L ₁₀	55.4	55.9	54.8	55.9
58.4	61.5	56.0	57.3		55.3	55.9	54.8	55.8
58.9	56.5	56.2	59.5		55.2	55.5	54.3	54.6



Noise Measurements in Moreno Valley (10:15am) Davis St

Source: Blodgett/Baylosis Environmental Planning


Actual Noise Levels During Measurement				Noise Measurement Results in Leq%				
1-25	26-50	51-75	76-100	L%	1-25	26-50	51-75	76-100
55.1	58.2	44.1	55.3	L ₉₉	55.6	62.0	55.9	55.3
51.7	52.9	43.8	46.8		55.5	59.1	52.8	53.2
46.8	59.1	45.5	43.4	L ₉₀	55.2	58.2	52.2	52.3
49.8	45.4	49.5	45.4		55.1	57.0	51.1	49.3
51.6	45.1	52.8	45.4		54.9	56.3	50.4	49.0
50.1	51.2	45.1	52.3		54.6	54.5	49.8	48.2
48.0	57.0	42.8	53.2		54.6	52.9	49.7	46.8
44.7	62.0	42.6	49.0		53.3	51.2	49.5	45.9
45.4	54.5	42.8	42.9		53.2	50.9	49.4	45.4
45.3	56.3	45.8	49.3		52.8	49.3	48.3	45.4
42.4	50.9	50.4	43.5		52.2	49.2	47.2	45.4
44.3	46.1	51.1	40.8	L ₅₀	52.0	46.4	45.8	44.5
45.3	46.4	49.7	43.2		51.7	46.1	45.5	44.4
51.3	43.6	45.1	42.0		51.6	45.4	45.1	43.9
54.6	42.8	47.2	41.6		51.3	45.1	45.1	43.5
52.2	42.6	49.8	44.4		50.1	44.0	44.9	43.4
52.8	41.8	44.9	43.9		49.8	43.6	44.1	43.2
53.3	41.0	42.7	44.5		48.0	42.8	44.0	42.9
55.5	41.2	41.8	45.9		46.8	42.7	43.8	42.9
55.2	41.9	42.8	45.4	L ₂₅	45.4	42.6	42.8	42.7
54.6	42.7	48.3	48.2		45.3	42.2	42.8	42.2
54.9	42.2	44.0	42.7		45.3	41.9	42.8	42.0
53.2	44.0	49.4	42.0	L ₁₀	44.7	41.8	42.7	42.0
52.0	49.2	52.2	42.2		44.3	41.2	42.6	41.6
55.6	49.3	55.9	42.9		42.4	41.0	41.8	40.8



Noise Measurements in Moreno Valley Nita Dr

Source: Blodgett/Baylosis Environmental Planning

Actual Noise Levels During Measurement				Noise Measurement Results in Leq%				
1-25	26-50	51-75	76-100	L%	1-25	26-50	51-75	76-100
76.2	52.5	50.5	71.5	L ₉₉	76.4	70.2	77.7	71.5
76.4	51.7	54.8	70.5		76.2	68.2	75.2	70.5
63.8	52.6	63.4	66.0	L ₉₀	71.6	67.4	73.4	66.0
60.0	51.9	73.4	62.9		70.5	65.4	72.8	63.2
56.4	51.5	75.2	58.9		69.4	65.3	72.3	62.9
55.4	50.3	71.3	57.4		68.9	64.0	71.7	61.1
60.0	49.0	72.3	56.5		66.1	63.7	71.3	60.4
61.8	49.3	77.7	56.1		65.0	63.6	70.8	59.3
62.4	50.4	72.8	59.3		63.8	63.1	70.3	58.9
60.8	49.5	71.7	60.4		63.8	61.8	69.2	58.1
63.8	56.1	70.3	63.2		62.4	58.4	68.8	57.4
69.4	61.8	68.3	61.1	L ₅₀	61.8	56.1	68.3	56.5
71.6	68.2	69.2	58.1		61.3	55.2	67.7	56.1
70.5	70.2	68.8	55.1		60.8	52.6	67.6	55.1
68.9	65.3	67.7	51.2		60.0	52.5	67.4	53.1
65.0	63.6	67.6	50.9		60.0	51.9	67.0	51.2
66.1	63.1	67.4	50.7		56.4	51.7	66.7	50.9
61.3	65.4	66.5	50.8		55.9	51.5	66.5	50.8
55.9	67.4	65.1	50.2		55.4	50.8	65.1	50.7
53.9	64.0	67.0	50.1	L ₂₅	54.6	50.4	64.4	50.2
54.6	63.7	70.8	49.7		53.9	50.3	63.4	50.1
53.6	58.4	66.7	48.6		53.9	49.8	63.2	49.7
53.9	55.2	64.4	48.6	L ₁₀	53.6	49.5	63.0	48.9
52.0	50.8	63.2	48.9		52.0	49.3	54.8	48.6
50.6	49.8	63.0	53.1		50.6	49.0	50.5	48.6



Noise Measurements in Moreno Valley along Heacock

Source: Blodgett/Baylosis Environmental Planning